



FIG. 1




FIG. 2

II - II CROSS - SECTION




FIG. 3

III - III CROSS - SECTION




FIG. 4




FIG. 5




FIG.6




FIG. 7

VII - VII




FIG. 8

VIII - VIII




FIG. 9

IX - IX





FIG. 10

GRAY SCALE DRIVE	CONVERSION TABLE															LIGHT EMISSION PATTERN																
	PDs	GD															SF 1	SF 2	SF 3	SF 4	SF 5	SF 6	SF 7	SF 8	SF 9	SF 10	SF 11	SF 12	SF 13	SF 14	SF 15	
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15																
FIRST	0000	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	●															
SECOND	0001	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	○	●														
THIRD	0010	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	○	○	●													
FOURTH	0011	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	○	○	○	●												
FIFTH	0100	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	○	○	○	○	●											
SIXTH	0101	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	○	○	○	○	○	●										
SEVENTH	0110	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	○	○	○	○	○	○	●									
EIGHTH	0111	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	○	○	○	○	○	○	○	○	●							
NINTH	1000	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○
TENTH	1001	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○
ELEVENTH	1010	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○
TWELFTH	1011	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○
THIRTEENTH	1100	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○
FOURTEENTH	1101	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○
FIFTEENTH	1110	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○
SIXTEENTH	1111	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○	○

● : ERASURE ADDRESS DISCHARGE ○ : SUSTAIN DISCHARGE LIGHT EMISSION

FIG. 11






FIG.12

FIG. 13




FIG.15

XV - XV




FIG. 16

XVI - XVI




FIG. 17

XVII - XVII





FIG. 18






FIG.19